

ASSEMBLY INSTRUCTIONS


ITEM NO: I3404-360WD-DRT 60" Writing Desk

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may come loose inside the carton during shipment.

WARNING! Before using this product, please read, understand, and follow these instructions. Failure to follow each of these assembly instructions precisely may result in damage to the product and / or injury to the consumer.



UNIT SHOULD BE INSTALLED BY 2 OR MORE PERSONS.




TOOLS REQUIRED (NOT PROVIDED) PHILLIPS SCREWDRIVER

HARDWARE LIST:				
No.	Description	Sketch	Quantity	
A	Bolt Ø5/16" x 1-3/4"	9	16 PCS	
В	Lock Washer Ø5/16"		16 PCS	
C	Flat Washer Ø5/16" x 3/4"	0	16 PCS	
D	Allen Wrench 4mm		1 PC	

COMPONENTS LIST:				
No.	Description	Sketch	Quantity	
1	Desk Top		1 PC	
2	Side Frame		2 PCS	

FUNCTIONALITY INSTRUCTION






ASSEMBLY INSTRUCTIONS

ITEM NO: I3404-360WD-DRT 60" Writing Desk


<u>STEP 1:</u> Remove the side drawers from the desk top: Fully extend the drawers, then press the plastic tabs down on the right and up on the left at the same time as shown below. While holding the tabs pressed down/up, pull the drawers out.



STEP 2: Put the desk top upside down on a soft surface.

<u>STEP 3:</u> Attach the side frames to the bottom of desk top by using 16 bolts (A), lock washers (B) and flat washers (C) with an allen wrench (D). Completely tighten all bolts.

STEP 4: Return the desk to the upright position.



STEP 5: Replace all of the drawers in desk top: Fully extend the slides from the desk top. Then align the slides on the drawers to the slides on the pedestals as shown. Push the drawers back in. You may have to slide the drawers in and out several times in order to properly align the ball bearings.

